


**ANACONDA Copper Company**

New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



March 25, 1980

Mr. A. F. Czarnowsky  
Area Mining Supervisor  
UNITED STATES DEPARTMENT OF INTERIOR  
GEOLOGICAL SURVEY  
P.O. Box 26124  
Albuquerque, New Mexico 87125

Re: Jackpile Mine Reclamation Plan  
Report - Fourth Quarter, 1979.

Dear Mr. Czarnowsky:

In accordance with the Jackpile Mine Reclamation Plan, we submit the following data for the Fourth Quarter of 1979:

1. Radiological Analysis of Ground and Surface Water.
2. Chemical Analysis of Ground and Surface Water.
3. Results of the Air Monitoring Program.
4. Results of the Ambient Radon Study.

Sincerely,

MEADE A. STIRLAND  
Manager, Environmental Health & Safety

MAS/jms  
Encls.